This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- (•) BLACK OR VERY BLACK AND WHITE DARK PHOTOS
 - GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




FIG 1




FIG 1B




FIG 1C

WALL/ROOF POLISHER

Ganxing Ke
Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS





FIG 2






FIG 3A




FIG 3B









FIG 3C

















FIG 6





FIG 6B



WALL/ROOF POLISHER Ganxing Ke 760,101 Atty Docket: JEEK1.001AUS Appl. No.: 10/760,101




FIG 7A




FIG 7B




FIG 8




FIG 9A




FIG 9B




FIG 10

WALL/ROOF POLISHER Ganxing Ke 760,101 Atty Docket: JEEK1.001AUS Appl. No.: 10/760,101




FIG 11




Fig 12

Ganxing Ke
Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS




FIG 12B




FIG 13

WALL/ROOF POLISHER Ganxing Ke
Appl. No.: 10/760,101 Atty Docket: JEEK1.001AUS

